## FFD-Info 8



## **Cleaning recommendation** for powder-coated surfaces

The cleaning of powder-coated surfaces should be done generally first with a soft dry cloth.

If pollution cannot be removed in this kind, the cloth can be moistened and also if necessary there can be used a ph-neutral cleaner.

Basically there have to be avoided any contact between the powder coatings and alkaline or acid substances. In this case especially the metallic powders show a high sensitive reaction.

If the usage of a special cleaner is necessary to eliminate certain pollutions we recommend to check the applicability of the cleaner at a hidden place first.

We do not guarantee for damages which are caused by incorrect cleaning. Exceptions require previous verifications.

Our technical data sheets are to advise you according to our latest state of knowledge. These information does not release you from own tests of our products in view to the ability for the intended procedures and applications. The sole of our products is an accordance with our terms of business and delivery.

DIN EN ISO 9001 I IATF 16949 I EMAS

FreiLacke I Emil Frei GmbH & Co. KG

Am Bahnhof 6 78199 Bräunlingen/Döggingen +49 7707 151-0

info@freilacke.de I www.freilacke.de