














Pictograms

In order to simplify the international communication, pictograms are used on the FreiLacke-labels. You find a short explanation of the pictograms following.

Powder Coating	Industrial Coating, Electro-deposition Coating, Durelastic
 <p>standard object temperature</p>	 <p>Industrial Coating standard object temperature</p>
 <p>outdoor use</p>	 <p>Industrial Coating and Durelastic mixing ratio (MR) parts per weight</p>
 <p>indoor use</p>	 <p>Industrial Coating and Durelastic stir up before use</p>
 <p>indoor use, limited outdoor use</p>	 <p>Durelastic additive</p>
 <p>cool and dry storage</p>	 <p>Industrial Coating, Electrodeposition Coating, Durelastic cool and dry storage</p>
 <p>Acryl – Powder Coating cool and dry storage</p>	 <p>System Coating</p>
 <p>System Coating</p>	